



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program April 13, 2010

Reviewed: 

Mine Name: Glenn Goff Property	Permit Number: S/039/0014
Operator Name: KSC Rocks	Inspection Date: March 17, 2010
Inspector(s): John Rogers and Lynn Kunzler	Time: 3:00 pm
Other Participants: none	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	X	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	X	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	X	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	X	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	X	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	X	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	X	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	X	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	X	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: none **Bond Amount:** \$5400 **Permit fee:** is up to date through 2009

Purpose of Inspection: Inspect for reclamation status.

Inspection Summary: The area has been regraded and revegetated in the fall of 2009. The grading is acceptable and revegetation is beginning to establish itself. It is still too early to see the overall success rate of revegetation. The landowner indicated that the road could remain as is. The area was clear of trash and equipment. The overall reclamation was good.

Photos were taken to document site conditions. Yes


Conclusions and Recommendations: DOGM will continue to monitor the site when in the area to see the establishment of the revegetation process. A partial bond release is recommended. A reserve of \$1000 should be held for additional revegetation, if current revegetation process does not thrive.

Inspector's Signature

JCR:vs

cc: KSC Rock - Steve Sorensen
Glen Goff - landowner

O:\M039-Sanpete\S0390014-GlenGoff\inspections\Insp-03172010.docpath






Looking east at quarry



Looking east at quarry



Looking south at quarry



Looking south at quarry